

# **SERVICE ALERT**

#### NO.: 0824 Rev C

**TO:** All G1000/G900X/G950 Owners and Operators

DATE: 20 November 2009

SUBJECT: GDU 104X CRS/BARO Knob Interference

**REVISION C:** Added note regarding Service Bulletin 0823 in Affected Products section

#### AFFECTED PRODUCTS

### NOTE

The knob interference issued described in this service alert is resolved by complying with Service Bulletin 0823 Revision C, therefore units that comply with SB0823 Rev C are not affected by this alert.

All G1000/G900X/G950 installations with the following 10-inch GDU 104X displays are affected:

Unit	Garmin Part Number	Affected Serial Number Range		
	011-00972-00	86500310 - 86503767		
GDU 1040	011-00972-02	87005059 - 87005312		
GD0 1040	011-00972-03	88900023 - 88904925		
	011-00972-03	106000265 - 106001037		
GDU 1042	011-01080-00	86850318 - 86851005		
GDU 1043	011-01079-00	86900317 - 86900748		
GDU 1044	011-01078-01	86960200 - 86960376		
GDU 1044B	011-01274-00	51200156 - 51201502		

### NOTE

GDU 104X installations with GDU software version 3.02 and later can view unit serial numbers on the AUX – SYSTEM STATUS page. Refer to Figure 1 for an example.

© Copyright 2009 Garmin Ltd. or its subsidiaries All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.

68 <b>U</b> I	(T DTK	<b>*</b>	TRK 267	ETE		AUX - 9	SYSTEM STATUS			
LR	U INFO,					ROME,		1		
	8	TATUS SEF	RIAL NUMBER	VERSION	ATRERA	ME				
GSA	PTCH CTL	<ul> <li>Image: A second s</li></ul>	66400083	2.13	SYS SOF	THARE VERSION				
GSA	PTCH MON	~	66400083	2.13	CRG PAR	rt Number				
GSA	PTCH TRH C	1	66400091	2.13	SYSTEM		205207688			
GSA	PTCH TRH H	1		2.13	CHECKL)	181	NOT AVAILABLE			
GSA	ROLL CTL	1	66380839	2.13				J		
GSA	ROLL MON	1	66300039	2.13	BASEMA			1		
GSA	YAH CTL	1	66300032	2.13		SION	WORLDWIDE			
GSA	YAH HON	<b>v</b>	66300032	2.13	VER	REION	2.00			
GTX	1	<b>v</b>		5.81			RPORATION 1995-2006			
GTX	2	<ul> <li>Image: A second s</li></ul>		5.01	SAFETA)					
GHX		×				SION	US 2.17		Example	
HED	1	1	86900500	€ 3.02	CYL	REION	0853		•	
NOV	1	1		4.00		FECTIVE	95-44-118		GDU 104X	
NAU	2	1		5.01		LIRES	31-JUL-08		<b>.</b>	
PFD	1	Ĵ.	86900546 <	9.02		ARHIN LTD. AND IT	S SUBSIDIARIES 2000		Serial Numbers	
PED	2	1	86900540	9.02	0/10110					
		<u> </u>			REG	SION	WORLDWIDE			
						MAP HPT AU	X NRST 000000			
LRU	ARFRH	DBASE			ANN TES	ST	(GERUIS	11 ·		
Figure 1										



If the GDU 104X serial number on the AUX – SYSTEM STAUS page displays "0" or if the GDU software version does not display the unit serial numbers, proceed to Step 1 of the IMMEDIATE ACTION REQUIRED section of this service alert.

The following G1000-equipped aircraft may include one or more of the affected GDU 104X displays listed above.

Cessna 172R/172S/182T/T182T/206H/T206H Cessna 350/400 Columbia 350/400 Diamond DA40/40F/40D/DA42 Mooney M20M/M20R/M20TN Piper PA 32 Saratoga Quest Kodiak 100 Hawker Beechcraft G36 Bonanza Hawker Beecncraft G58 Baron Tiger AG-5B

All G900X/G950 aircraft installations may also include one or more of the affected GDU 104X displays listed above.

### DESCRIPTION

Garmin has identified an issue, whereby the large (outer) BARO knob and the small (inner) CRS knob may interfere with each other.




Figure 2

### **IMMEDIATE ACTION REQUIRED**

PFD and MFD CRS/BARO Knob Interference Test

- 1. Apply power to the G1000/G900X/G950.
- 2. Press the CDI softkey on the Primary Flight Display(s) (PFD) to enter VOR mode on the HSI.
- 3. Rotate the large (outer) BARO knob (refer to Figure 2) a minimum of three complete revolutions in each direction while monitoring the Horizontal Situation Indicator/Digital Course Indicator (refer to Figure 3) on the PFD. If a change in the Horizontal Situation Indicator/Digital Course Indicator is produced while turning the BARO knob contact your local Garmin Service Center or OEM Dealer to replace the knobs.




In some installations the Digital Course Indicator does not display unless the field is actively being edited. In these instances, if the Digital Course Indicator does not appear while turning the BARO knob, no interference is present.

- 4. Rotate the small (inner) CRS knob (refer to Figure 2) a minimum of three complete revolutions in each direction while monitoring the Barometric Altimeter Setting (refer to Figure 3) on the PFD. If a change in the Barometric Altimeter Setting is produced while turning the CRS knob contact your local Garmin Service Center or OEM Dealer to replace the knobs.
- 5. Repeat Steps 3 and 4 for each affected GDU.

## NOTE

When testing the Multi Function Display (MFD), the indications must be monitored on the PFD.



### **MAINTENANCE RECORDS**

If no interference is observed, the pilot performing the check should make the following aircraft logbook entry:

On dd/mm/yyyy the CRS/BARO knobs on installed displays were checked for interference with none found per Garmin Service Alert 0824. Signed - (pilot name here)