

SERVICE ADVISORY

NO.: 1026 Rev A

TO: G3X Owners/Operators

DATE: July 19, 2010

SUBJECT: G3X GSU Software Version 2.13

AFFECTED PRODUCTS

All G3X systems with GSU software versions prior to 2.13 are affected.

DESCRIPTION

Garmin has become aware of an issue regarding G3X GSU 73 software versions prior to 2.13 that may result in incorrect AHRS operation when the pitch/roll offset is greater than zero degrees.

PILOT ACTION

Do not fly while relying on the affected products until the procedures below have been completed.

RESOLUTION

NOTE

Refer to www.garmin.com for the latest G3X software version and G3X Installation Manual (190-01115-01).

Load G3X GDU 37X software version 3.20 (required for GSU 73 software version 2.13), and GSU 73 software version 2.13 as described in Section 7.2 of the G3X Installation Manual (Garmin P/N 190-01115-01).

Perform the following calibration procedures, as described in the Section 9.3 of the G3X Installation Manual (Garmin P/N 190-01115-01), after loading GDU 37X Software Version 3.20 and GSU 73 Software Version 2.13.

- Calibration Procedure A AHRS Orientation
- Calibration Procedure B Pitch/Roll Offset Compensation
- Calibration Procedure D Magnetometer Calibration

© Copyright 2010 Garmin Ltd. or its subsidiaries All Rights Reserved