



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GTN™ Xi Owners and Operators
DATE: March 1, 2023
SUBJECT: GTN™ Xi Main Software Version 20.30

COMPLIANCE

Recommended: Compliance with TSO Service Bulletin 22108 is recommended at the next maintenance interval.

PURPOSE

GTN Xi Series Main software version 20.30 contains the following changes:



NOTE

If installed, GI 275 Software Version 2.60 (or later) and G500(H)/G600/G700 TXi Software Version 3.50 (or later) is recommended before updating to GTN Xi Software Version 20.30.

- Fixed an issue described in Garmin Service Advisory 22018, where an airport that is within glide range as depicted on the map may not be a selectable destination if it is less than 2NM away while flying at low altitude (less than 2500 feet AGL)
- Fixed an issue described in Garmin Service Advisory 21124, when selecting some ILS approaches on the GTN Xi navigator, the GFC 500 is not able to capture the glideslope
- Fixed an issue described in Garmin Service Advisory 22003, where the flight plan will not change when airborne and using the graphical flight plan editing feature on the active leg of a flight plan that contains an altitude constraint
- Expanded the database sync feature to support coordinated restarts and status reporting across GTN Xi, G500(H)/G600/G700 TXi (v3.50 or later) and GI 275 (v2.60 or later)
- Added Digital signatures to all database files



NOTE

This feature requires GTN Xi System ID. If using Jeppesen Database Manager, the account must be updated to include the System ID.

- Added GI 275 to the LRUs that support remote database confirmation
- Added support for 100Mb Ethernet for database sync between GTN Xi, G500(H)/G600/G700 TXi (v3.50 or later) and GI 275 (v2.60 or later)

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

- Added display of Software Key Region version, Software Key Region part number, Database Key Region version and Database Key Region part number to System Information in configuration mode
- Updated user interface for Flight Stream 510 Wi-Fi security to encourage stronger passwords
- Expanded configuration mode Diagnostic Logs to allow deletion of the stored Flight Data Logs
- Expanded Route waypoint types to include fly-over waypoints
- Changed flight plan waypoints that are used for transitions to be shown in gray text on the flight plan page
- Fixed an issue with chart overlay flickering on the map when on the ground. The chart overlay on the map displays only when in air
- Restored the functionality for Flight ID to be editable with the knob on GTN 650Xi
- Reworded the nearest airport list to display “No Glide Information Available” instead of “No airports within Glide Range” when Smart Glide™ is configured but inactive and not displaying the glide range ring
- Improved the lighting bus input processing to protect against inputs above the maximum value configured by the lighting curve
- Fixed an issue where the waypoint discrete output was being incorrectly set on segment transitions on some course reversals
- Changed descriptions of VOR/DME, VOR, NDB/DME, NDB, and TACAN approaches for LNAV with advisory vertical guidance to only append “+V” instead of “LNAV+V”
- Improved determining the altitude constraints for a standard arrival that shares a common waypoint with an approach to load the best constraint, either the constraint that satisfies both procedures or a composite of the two constraints. If the best constraint is not found, the standard arrival constraint is used.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

PRODUCTS AFFECTED

The following units are affected:

Table 1. Products Affected

Model	Appliance P/N
GTN 625Xi	011-04629-00
GTN 635Xi	011-04630-00 011-04630-01
GTN 650Xi	011-04631-00 011-04631-01 011-04631-30 011-04631-31 011-04631-60 011-04631-61
GTN 725Xi	011-04632-00
GTN 750Xi	011-04634-00 011-04634-01 011-04634-30 011-04634-31 011-04634-60 011-04634-61

WARRANTY INFORMATION

This service bulletin is not warranty reimbursable.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.