GARMIN.

1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY
NO.: 1609 Rev A

TO:	Owners and Operators of GNS 400W/500W Series Units
DATE:	February 16, 2016
SUBJECT:	TCAD Approach Mode Command Is Not Properly Labeled

PRODUCTS AFFECTED
GNS 400W/500W Series units with software version 5.00 to 5.30 interfaced to a Garmin GDL 88 that is interfaced to an Avidyne (Ryan) TAS 6XX (9900BX) are affected.

ISSUE
When enabling or disabling TCAD APR Mode on the GNS Traffic page, the selection does not display "Disable TCAD APR Mode?". The selection always displays "Enable TCAD APR Mode?".
Refer to Figure 1.

Figure 1 – TCAD APR Mode Selection

PILOT ACTION
Use the GNS Traffic page to make sure which TCAD mode is selected. The TCAD mode is displayed in the upper right corner of the GNS Traffic page. Refer to Figure 2.

Figure 2 – TCAD APR Mode GNS Traffic Page

TCAD Modes:
TCAD STBY – in white
TCAD OPER – in green
TCAD FAIL – in yellow
TCAD TEST – in white
TCAD APR – in green
TCAD GND – in green

RESOLUTION
A future software release will correct this issue.