



# SERVICE ADVISORY

NO.: 0851 Rev A

**TO:** All Garmin Aviation Service Centers and Owners/Operators of Garmin GMX 200 Units  
**DATE:** December 04, 2008  
**SUBJECT:** GMX 200 Display Color Shift

---

## AFFECTED PRODUCTS

All GMX200 Series Units

## DESCRIPTION

Garmin has identified an issue with the operation of GMX 200 Units:

When the display backlighting is set to the maximum level and the GMX 200 is operating in high temperatures there may be a noticeable color shift to some of the colors displayed on the unit. If a change in colors does occur, reducing the backlight intensity will resolve the issue.

## RESOLUTION

To reduce the backlight intensity, press down on the "-" side of the power rocker switch located on the upper right of the unit, until the color shift is no longer apparent.



Garmin and the FAA have concurred that this does not affect safety of flight. This condition will be corrected in upcoming display board software that will require the unit to be returned to the factory for installation and color calibration.

© Copyright 2008  
Garmin Ltd. or its subsidiaries  
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.