



SERVICE ADVISORY

NO.: 1137 Rev A

TO: Dealers and Owners/Operators with GTN 6XX/7XX Units
DATE: July 7, 2011
SUBJECT: GTN 6XX/7XX Units Installed with Dual GTX 32 Transponders

AFFECTED PRODUCTS

GTN 6XX/7XX Units with Main Software Version 2.00 installed with dual GTX 32 transponders.

DESCRIPTION

When the GTN 6XX/7XX unit is installed with dual GTX 32 transponders the GTN will erroneously display the following message:

“TRANSPONDER – Transponder 1 and 2 Mode S addresses do not match”

This message does not affect the operation of the GTN 6XX/7XX or the GTX 32 transponders.

In dual GTX 33 Mode S transponder installations (the GTX 32 is a mode C transponder) the above message is designed to appear if the Mode S addresses entered for each transponder during configuration do not match.

RESOLUTION

Garmin plans to correct this issue in a later software version.

© Copyright 2011
Garmin Ltd. or its subsidiaries
All Rights Reserved

Perspective™ is a trademark of Cirrus Design Corporation. Prodigy™ is a trademark of Embraer S.A. Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.