



SERVICE ADVISORY

NO.: 1155 Rev A

TO: Owners/Operators with GTN 6XX/7XX Units

DATE: November 28, 2011

SUBJECT: GTN 6XX/7XX Units and Approaches with Holds/Course Reversals at the Initial Approach Fix

AFFECTED PRODUCTS

GTN 6XX/7XX Units with Main Software Version 2.00.

DESCRIPTION

When flying an approach multiple times with a Hold/Course Reversal at the Initial Approach Fix (IAF), the Hold/Course Reversal may not be properly re-inserted into the flight plan on the second and subsequent uses of the approach.

PILOT ACTION

Until updated software is installed: When flying the same approach multiple times, always remove the approach on the Flight Plan Page and reload approaches from the Procedure Page.

RESOLUTION

Garmin plans to correct this issue in a later software version.

© Copyright 2011
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.