



## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered Garmin Owners/Operators of G1000-equipped Hawker Beechcraft King Air C90A/C90GT/C90GTi aircraft modified in accordance with STC # SA01456WI-D MDL Rev 6, Rev 7 or Rev 8

**DATE:** 29 January 2013

**SUBJECT:** STC #SA01456WI-D MDL Revision 9 Update

### **COMPLIANCE**

Recommended

### **PURPOSE**

Service Bulletin 1305 provides instructions for incorporating improvements to the G1000 C90A/C90GT/C90GTi installation that are approved by MDL Rev 9.

Improvements provided by MDL Rev 9 include a modification to the standby instrument dimming control circuitry, which increases the standby instrument lighting adjustment range.

### **PRODUCT AFFECTED**

G1000-equipped Hawker Beechcraft King Air C90A/C90GT/C90GTi aircraft modified in accordance with STC # SA01456WI-D MDL Rev 6, Rev 7 or Rev 8.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.