



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners/Operators of King Air 300/B300 aircraft with G1000 under
Garmin STC and Garmin Service Centers

DATE: June 17, 2013

SUBJECT: This communication is intended to inform Garmin aviation customers of
service bulletin SB1335

COMPLIANCE

Mandatory This service bulletin must be performed for all affected products by
June 17, 2014 or prior to 1000 hours time in service (whichever comes first).

PURPOSE

GSM 9100 servo gearbox units marked as Mod Level 0 or Mod Level 1 (as listed in
Affected Products section) may be subject to premature wear of the gear shaft.

DESCRIPTION

SB1335 provides instructions to replace any affected GSM 9100 servo gearbox unit by
June 17, 2012 or 1000 hours time in service (whichever comes first). Only GSM 9100
servo gearboxes marked as Mod Level 2 or greater should be installed as a
replacement.

AFFECTED PRODUCTS

GSM 9100 servo mount units with part number 010-00803-00 (011-02214-00) and
marked as Mod Level 0 (Figure 1) or Mod Level 1 (Figure 2) on the serial tag are
affected by this bulletin.



Figure 1 - Mod Level 0



Figure 2 - Mod Level 1

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for
questions regarding this notification. This service notification and associated bulletin/advisory product changes can
only be implemented through Garmin's authorized dealer and service center network. This document is not a
substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.