



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GTR 225/GNC 255 Owner/Operators
DATE: February 26, 2014

SUBJECT: GTR 225/GNC 255 Software Upgrade to COM Software Version 2.13

CERTIFICATION

APPROVAL: TSO Authorization

COMPLIANCE

Recommended.

PURPOSE

COM Software Version 2.13 contains the following changes from Version 2.12:

- Reduced noise burst (open squelch) that can occur after transmitting, flip-flopping frequencies, or exiting monitor mode when the receiver is set for high sensitivity.

The following service documents have been resolved:

- Corrected issue with the MIC1 and MIC2 gain settings being transposed in Configuration Mode (Installation Bulletin 1359)
- Corrected issue in limited circumstances where a monitored COM frequency may prevent the pilot from receiving communication on the active COM frequency (Service Advisory 1370)

PRODUCTS AFFECTED

The following units are affected:

	GTR 225	GTR 225A	GTR 225B	GNC 255A	GNC 255B
Garmin PN	011-02718-00	011-02807-00	011-02808-00	011-02806-00	011-02719-00
COM SW PN/ COM SW Version	006-B1061-07/ 2.13	006-B1061-07/ 2.13	006-B1061-07/ 2.13	006-B1061-07/ 2.13	006-B1061-07/ 2.13

DESCRIPTION

This software service bulletin describes the process for upgrading the GTR 225/GNC 255 Series Unit's COM Software to Version 2.13.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.