

SERVICE ADVISORY

NO.: 1409 Rev A

TO: Owners/Operators of Garmin GTN 6XX/7XX Units

DATE: March 14, 2014

SUBJECT: GTN 6XX/7XX Occasional Momentary Screen Flicker

AFFECTED PRODUCTS

This issue affects GTN 625/635/650 and GTN 725/750 Units with Main Software Version 3.00 through Version 5.00.

ISSUE

During normal operation, a portion of the GTN display may occasionally exhibit a momentary flicker. This can occur on any page of the GTN series unit, but does not affect the operation of the unit.

RESOLUTION

Garmin plans to correct this issue in a future software release.