



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered GTX 23, GTX 33(D)(ES)(H), and GTX 330(D)(ES) owners
DATE: August 19, 2014
SUBJECT: Service Bulletin 1435, Software Version 7.04 available for GTX 23, GTX 33(D)(ES)(H), and GTX 330(D)(ES) products (not applicable to G900X, G950, G1000, Cirrus Perspective®, or Embraer Prodigy™ installations)

COMPLIANCE

Mandatory: This Service Bulletin must be accomplished by August 15, 2015 or the next scheduled service interval; whichever occurs first.

PRODUCTS AFFECTED

This bulletin is applicable to GTX 23, GTX 33(D)(ES)(H), & GTX 330(D)(ES) units with Software Version 7.03 or previous software versions not installed in a Garmin Integrated Flight Deck system (G1000, G1000H, G950, G900X, Cirrus Perspective™, and Embraer Prodigy® Integrated Flight Deck Systems). The GTX 330(D)(ES) current software version is displayed at power up, on the unit's front panel. The GTX 23/ GTX 33(D)(ES)(H) software version is displayed on the remote screen of the controlling LRU (e.g. GTN) Startup/Self-Test Page.

This Service Bulletin authorizes this software version in the applicable LRU(s). The installer or TC/STC holder (if any) must determine applicability and provide for airworthiness at the installation level in accordance with FAA requirements.

PURPOSE

This Service Bulletin incorporates new unit Software Version 7.04 for GTX 23, GTX 33(D)(ES)(H), & GTX 330(D)(ES) units. Software Version 7.04 incorporates the below functionality.

- Ensures Flight ID changes are properly transmitted to ATC
- Decreases the time needed to communicate small changes in the horizontal radius of containment.
- Ensure proper function of devices connected to the GTX via RS-232

DESCRIPTION

This modification consists of accessing the Dealer Resource Center portion of the Garmin website (<https://dealers.garmin.com>) and uploading new software to the unit.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.