



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered GTX 328 owners
DATE: March 31, 2015
SUBJECT: Software Version 7.04 available for GTX 328 units

COMPLIANCE

Mandatory: This Service Bulletin is mandatory only for GTX 328 units installed with a Garmin GTN 6XX/7XX unit, where the GTN 6XX/7XX unit provides control of the GTX 328.

Optional: For all other installations this Service Bulletin may be incorporated at the owner's expense.

PRODUCTS AFFECTED

This bulletin is applicable to GTX 328 units with Software Version 7.03 or previous software versions. The GTX 328 current software version is displayed at power up, on the unit's front panel.

This Service Bulletin authorizes this software version in the applicable LRU(s). The installer or TC/STC holder (if any) must determine applicability and provide for airworthiness at the installation level in accordance with FAA requirements.

PURPOSE

This Service Bulletin incorporates new unit Software Version 7.04 for GTX 328 units. Software Version 7.04 incorporates the following functionality.

- Ensures proper function of devices connected to the GTX 328 via RS-232
- Ensures proper initialization of standby mode at power-on when an external standby input is used.

The following item was incorporated in GTX 328 Software Version 7.03 (which is now obsolete), and is also included in GTX 328 Software Version 7.04.

- Ensures Flight ID changes are properly transmitted to ATC

DESCRIPTION

This modification consists of uploading new software to the GTX 328, visit a Garmin Dealer or Service Center for assistance.