



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record for the GDL 88
DATE: August 20, 2014
SUBJECT: GDL 88 Software Upgrade to System Software Version 3.00

CERTIFICATION

APPROVAL: TSO Authorization (see Approval section of SB1441 for details)

COMPLIANCE

Mandatory for all GDL 88 units.

See STC SB1452 for information about compliance for STC SA02119SE.

PURPOSE

This Service Bulletin announces the availability of GDL 88 System Software Version 3.00 and supersedes Software Service Bulletin 1371

GDL 88 System Software Version 3.00 contains the following changes from Version 2.06:

- Required update to improve 1090 MHz Mode S Extended Squitter receiver message processing
- Support for Flight Stream 110 and Flight Stream 210

PRODUCTS AFFECTED

The following GDL 88 units are affected:

	GDL 88	GDL 88 w/WAAS	GDL 88D	GDL 88D w/WAAS
Garmin PN	011-02369-00	011-02370-00	011-02371-00	011-02372-00
System SW PN/ System SW Version	Versions prior to 006-B0684-10/ 3.00			

DESCRIPTION

This software service bulletin describes the process for upgrading the GDL 88 Series Unit's System Software to Version 3.00.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.