



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered GSM 9100 equipped Garmin integrated flight deck owners and operators
DATE: July 30, 2014
SUBJECT: Service Bulletin 1445 GSM 9100 Mod 3

COMPLIANCE

Mandatory. Service Bulletin 1445 must be accomplished before December 31, 2014.

PRODUCTS AFFECTED

All GSM 9100 products are affected.

PURPOSE

Three screws on the GSM 9100 baseplate could become loose.

DESCRIPTION

This modification consists of gaining access to the GSM 9100, inspecting for signs of contamination, applying Loctite® to the three baseplate screws, and torquing the screws to the indicated torque specification.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.