

SERVICE ADVISORY

NO.: 1516 Rev B

TO: Owner/Operators of G1000 equipped Diamond DA 40 and DA 40F aircraft

DATE: May 6, 2015

SUBJECT: Loss of Engine Indication System (EIS)

REVISION B: Clarified products affected list and added reference to Garmin STC Service Bulletin 1534

PRODUCTS AFFECTED

G1000-equipped Diamond DA40 and DA40F aircraft equipped with the following system software versions are affected:

- 0321.24 or earlier versions
- 0369.13 or earlier versions

ISSUE

Loss of EIS may occur during extended (> 5 seconds) engine shutdowns during flight (see Figure 1). EIS immediately appears after engine restart.

NOTE

The engine will restart normally without the EIS information.

Missing EIS



Figure 1 – Loss of EIS Example

RESOLUTION

Contact a Garmin dealer for inclusion of Garmin STC Service Bulletin 1534.

NOTE

Garmin STC Service Bulletin 1534 does not cover software version 0321.24 for corrective action.

© 2015 Garmin Ltd. or its subsidiaries.
This work is licensed under a
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.