



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record of GTX 33X and GTX 3X5(R) Products
DATE: October 25, 2016
SUBJECT: GTX 3X5(R) main software version 2.05, ADS-B software version 2.05, and new standard rack part number for GTX 3X5 units
CERTIFICATION APPROVAL: STC SA01714WI MDL Revision 9

COMPLIANCE

Optional

PURPOSE

Major details of STC SA01714WI, GTX 33X and GTX 3X5(R) with ADS-B AML STC *MDL* Revision 9 are:

- Software fix for GTX 3X5 resetting at heading 360 while interfaced to Apsen displays issue
- Software fix for TIS-A processing which generated a failure depending on available intruder data issue

PRODUCTS AFFECTED

GTX 335/335R/345/345R (GTX 3X5(R)) and GTX 33/33D/330/330D (GTX 33X) units installed using Part 23 ADS-B AML STC SA01714WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.