



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record of G5000-equipped Beechcraft Model 400A Series Aircraft
DATE: March 13, 2017
SUBJECT: Yaw Servo Cable Clamp Nut Torque Change
CERTIFICATION:
APPROVAL: STC ST01821WI

COMPLIANCE

MANDATORY – Compliance with this Service Bulletin is mandatory at next opportunity, not to exceed 200 flight hours. This modification is warranty reimbursable with a deadline of September 13, 2017.

PURPOSE

Yaw servo cable tension may change due to cable clamp movement.

PRODUCTS AFFECTED

Beechcraft Corporation Model 400A Beechjet aircraft modified with the Garmin G5000 Integrated Flight Deck (STC ST01821WI Master Drawing List, Revisions 1 through 6) before the publication date of this service bulletin are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.