



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GMA 342/345 Owners of Record
DATE: May 5, 2017
SUBJECT: GMA 342/345 Software Version 2.10
CERTIFICATION
APPROVAL: TSO Authorization

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

Software Version 2.10 fixes a problem during power-up that results in high music volume for the pilot, copilot, and passengers.

PRODUCTS AFFECTED

GMA 342 (011-03520-10) and GMA 345 (011-03520-00) units with Software Version 2.00 (or earlier) are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.