



## **AVIATION SERVICE DOCUMENT NOTIFICATION**

**TO:** Registered Garmin GFC 600 Autopilot Owner and Operators  
**DATE:** October 31, 2018  
**SUBJECT:** Servo Cable Clamp Nut Torque Change for the GFC 600 Autopilot  
**CERTIFICATION**  
**APPROVAL:** STC SA01844WI

### **COMPLIANCE**

Recommended: Compliance with this service bulletin is recommended at the next opportunity, not to exceed next annual maintenance check.

### **PURPOSE**

Increase the torque on the servo cable clamp nuts.

### **PRODUCTS AFFECTED**

All aircraft with the GFC 600 autopilot installed per STC SA01844WI using Master Drawing List (MDL) 005-01009-01 Revisions 1 through 6 are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.