

SERVICE ALERT

TO: TOLD equipped G3000/G5000 Owners and Operators

DATE: November 1, 2019

SUBJECT: Takeoff/Landing Distance (TOLD)

REVISION B: Added Resolution

PRODUCTS AFFECTED

All G3000 and G5000 systems with TOLD are affected.

ISSUE

Some runways have an Accelerate and Stop Distance Available (ASDA) that is shorter than the Takeoff Run Available (TORA). For these runways the TOLD function uses the wrong data to determine available takeoff runway length.

PILOT ACTION

Refer to the Aeronautical Information Manual (AIM) for additional details on TORA and ASDA. Review the runway distance value used by TOLD for takeoff calculation and manually override if a shorter ASDA field distance is charted for the runway.

RESOLUTION

This issue is fixed in Navigation Database Cycles 1912 (effective 11/7/19) and later.