



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G3X Touch Owner and Operators
DATE: August 16, 2019
SUBJECT: G3X Touch for Certificated Aircraft, Software Version 8.30
CERTIFICATION AUTHORIZATION: STC SA01899WI

COMPLIANCE

Recommended: This STC Service Bulletin is recommended for certified G3X systems installed with the GFC 500 autopilot pitch trim servo.

For all other installations this STC Service Bulletin is optional and may be incorporated at the owner's discretion.

PURPOSE

MDL revision 3 includes G3X Touch Software Version 8.30. G3X Touch Software Version 8.30 corrects an issue that causes the GFC 500 autopilot to disengage when running pitch auto-trim.

PRODUCTS AFFECTED

G3X Touch systems installed using FAA STC SA01899WI, Master Drawing List (MDL) 005-01320-00, are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.