



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GTX 45R and GTX 345 Series Owner and Operators
DATE: October 29, 2019
SUBJECT: GTX 45R and GTX 345 Series ADS-B Software Version 3.13

CERTIFICATION

AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Recommended: Garmin recommends the incorporation of this service bulletin at the next scheduled service interval.

PURPOSE

GTX 45R and GTX 345 Series ADS-B Software Version 3.13 fixes an issue where some traffic targets may be missed when over 200 targets are in range.

PRODUCTS AFFECTED

The following GTX 45R and GTX 345 series units are affected:

Table 1. Products Affected

Model	Appliance P/N
GTX 345	011-03302-0()
GTX 345 GPS	011-03302-4()
GTX 345R	011-03303-0()
GTX 345R GPS	011-03303-4()
GTX 345 NV	011-03302-2()
GTX 345 NV, GPS	011-03302-6()
GTX 345D	011-04333-00
GTX 345DR	011-04334-00
GTX 45R	011-04287-0()

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.