

## SERVICE ADVISORY

NO.: 20132 Rev C

**TO:** GI 275 Owners and Operators  
**DATE:** June 15, 2021  
**SUBJECT:** Distance To DME  
**REVISION C:** Updated Resolution

---

### PRODUCTS AFFECTED

All GI 275 products with software versions 2.21 and earlier, with an HSI page and interfaced to a GTN or GNS series unit are affected.

### ISSUE

When the localizer is tuned and a GPS flight plan is loaded, the GI 275 provides a distance to the tuned localizer station. It does not provide a distance to the DME station.



### ACTION

For DME distance, use a receiver capable of providing DME station distances. If the aircraft is not equipped with a DME receiver, use the GPS waypoint distance provided by the navigator.

### RESOLUTION

This has been fixed in GI 275 Software Version 2.32.