

1200 E. 151st Street Olathe, KS 66062 913-397-8200

SERVICE ALERT

NO.: 21113 Rev B

TO:	Experimental and Light-Sport Aircraft G5 Electronic Flight Instrument Aircraft Owners and Operators
DATE:	December 21, 2021
SUBJECT:	Inoperative Backup Battery Indication
REVISION B:	Added Resolution

PRODUCTS AFFECTED

Garmin G5 Electronic Flight Instruments with software version 7.10 (and earlier) installed in Experimental and Light-Sport Aircraft installed with a backup battery with the 'Show Battery Status' configuration set to 'When Using Battery' are affected.



NOTE

This Service Alert does not apply to certified G5 installations. Certified G5 installations must follow approved AFMS procedures.

<u>ISSUE</u>

The G5 will not show the battery status field (or only intermittently show the battery status field) in response to an inoperative battery or battery fault.

© 2021 Garmin Ltd. or its subsidiaries. This work is licensed under a <u>Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.</u>

Service Alert 21113 December 21, 2021 I



1200 E. 151st Street Olathe, KS 66062 913-397-8200

<u>ACTION</u>

Do the following before any flight into Instrument Flight Conditions (IMC):

- 1. Push the Power button on the G5 attitude indicator.
- 2. Make sure the battery status indicator is green on the G5 attitude indicator.





No Battery Detected



Valid Battery Indication

WARNING

If a green battery status is not shown, or no battery is detected, do not fly into IMC.

RESOLUTION

This issue has been fixed in G5 Software Version 7.70. Refer to Garmin Service Bulletin 21107.



NOTE

Garmin recommends the steps described in the Action section be followed before any flight into IMC for all G5 software versions. This will be documented in a future revision of the G5 Electronic Flight Instrument Pilot's Guide for Non-Certified Aircraft (Garmin P/N 190-02072-00).

© 2021 Garmin Ltd. or its subsidiaries. This work is licensed under a <u>Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.</u>

Service Alert 21113 December 21, 2021 Page 2-2 Revision B