

1200 E. 151<sup>st</sup> Street Olathe, KS 66062 913-397-8200

**AVIATION SERVICE DOCUMENT NOTIFICATION** 

TO: Garmin G5000-equipped Textron Aviation Inc. Model 560XL Owners and

Operators

**DATE:** March 29, 2021

SUBJECT: G5000 System Software Version 3343.02, FANS 1/A and ACARS functions, and

Reactive Windshear feature for Textron Aviation Inc. Model 560Excel/XLS

**CERTIFICATION** 

AUTHORIZATION: STC ST01918WI MDL Revision 14

## **COMPLIANCE**

Optional: This STC Service Bulletin may be incorporated at the owner's discretion.

## **PURPOSE**

STC ST01918WI MDL Rev 14 provides software and hardware updates to support the optional FANS 1/A and ACARS functions for G5000-equipped Textron Aviation Inc. (Cessna) Model 560 Excel/XLS aircraft.

STC ST01918WI MDL Rev 14 also provides the optional Reactive Windshear configuration as opposed to the previously approved standard configuration in the 560XL baseline configuration.

System Software Version 3343.02 provides the following:

- FANS 1/A and ACARS (Optional)
- Reactive Windshear (Optional)



## NOTE

Reactive Windshear was included in the 560XL baseline configuration in G5000 System Software Version 3343.01.

Hardware upgrades include the GRS 56 #2 Iridium Transceiver to support FANS 1/A and ACARS functions (Optional).

## **PRODUCTS AFFECTED**

G5000-equipped Textron Model 560XL aircraft with System Software Version 3343.00 and 3343.01 are affected.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.