

1200 E. 151<sup>st</sup> Stree Olathe, KS 66062 913-397-8200

# SERVICE ADVISORY

NO.: 2167 Rev C

**TO:** GFC 600 AFCS Owners and Operators

Removed Resolution

DATE: January 12, 2024
SUBJECT: Overspeed Protection

## **PRODUCTS AFFECTED**

**REVISION C:** 

Garmin GFC 600 AFCS installed in Textron Aviation (Beechcraft) C90 are affected.

### **ISSUE**

Overspeed Protection will not engage until 226 KIAS. This is above the published Vne of the C90.

### **ACTION**

Never exceed the manufacturer published airframe speed limits.

#### **RESOLUTION**

As previously stated in Rev B of this Service Advisory, GMC 605 Software Version 2.85 (Garmin STC Service Bulletin 23099) does <u>not</u> fix this issue.

This will be fixed in a future software release.

© 2024 Garmin Ltd. or its subsidiaries.

This work is licensed under a

Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License..