

SERVICE ADVISORY

NO.: 2191 Rev C


TO: G500/G600 TXi Owners and Operators
DATE: January 31, 2022
SUBJECT: Indicated Airspeed (IAS) and Vertical Speed (VS) Bugs
REVISION C: Added Resolution

PRODUCTS AFFECTED

G500/G600 TXi systems with software versions 3.22 and later interfaced to a GFC 500 are affected.

ISSUE

The IAS bug always indicates the IAS flight director mode is activated, even when the IAS flight director mode is not activated.



Solid IAS Bug Indicating the IAS Flight Director Mode is Activated

The VS bug always indicates the VS flight director mode is activated, even when the VS flight director mode is not activated.



Solid VS Bug Indicating the VS Flight Director Mode is Activated

© 2022 Garmin Ltd. or its subsidiaries.
This work is licensed under a
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.

SERVICE ADVISORY

ACTION

Be aware the IAS and VS flight director always appears as activated.

RESOLUTION

This has been fixed in G500/G600 TXi Main Software Version 3.40.