



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GFC 500 Textron Aviation (Beech) H35 and J35 Owners and Operators
DATE: February 25, 2021
SUBJECT: Replacement of Yaw Servo Cable Clamps

COMPLIANCE

MANDATORY – Compliance with STC Service Bulletin 22024 is mandatory at the next 100-hour or annual inspection, not to exceed 3 months.

PURPOSE

The H35 and J35 airframes have 0.125-inch diameter rudder cables. The GFC 500 Yaw Damper Kit K11-00024-14 came with bridle cable clamps intended for 0.156-inch diameter cables. The H35 and J35 aircraft require 0.125-inch diameter cable clamps to properly connect the yaw servo bridle cable to the rudder cable.

PRODUCTS AFFECTED

Textron Aviation (Beech) H35 and J35 models with the optional yaw damper installed per GFC 500 Autopilot with Electronic Stability and Protection Part 23 AML STC (STC SA01866WI, Master Drawing List, Revisions 58 through 69) are affected.

WARRANTY INFORMATION

This modification is warranty reimbursable with a deadline of August 31, 2022.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.