



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GTN™ 6XX/7XX Owners and Operators
DATE: March 3, 2022
SUBJECT: GTN™ 6XX/7XX Main Software Version 6.72 and GPS Software Version 8.3

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion.

PURPOSE

This STC Service Bulletin provides notification of the FAA STC SA02019SE-D Master Drawing List GTN 6XX/ 7XX Part 23 AML STC Rev. 31 for the following:

- GTN 6XX/7XX Main Software Version 6.72
 - The "Enable ES" button on the transponder menu has been relabeled "ADS-B Out."
 - Fixed an issue related to turn alerting logic when transitioning onto a direct-to fix (DF) leg from a fly-over waypoint, the alerted course is now the DF leg course.
 - Fixed an issue when in a dual GTN installation with the CDI key configured to disabled, the Top of Descent aural annunciation now only plays on a single GTN.
 - Added DB sync support with GNX™ 375.

GPS/WAAS Software Version 8.3 corrects the MSAS range rate corrections issue identified in Garmin Service Advisory 20109 Rev B and restores MSAS to the set of allowed SBAS service providers.

PRODUCTS AFFECTED

GTN 6XX/7XX systems installed under the GTN 6XX/7XX Part 23 AML FAA STC SA02019SE-D are affected.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.