



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: G500(H)/G600/G700 TXi Owners and Operators
DATE: April 11, 2022
SUBJECT: G500(H)/G600/G700 TXi Main Software Version 3.41
CERTIFICATION AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Optional. Garmin Service Bulletin 22038 is optional and may be incorporated at the owner's discretion.

PURPOSE

G500(H)/G600/G700 TXi Main Software Version 3.41 contains the following changes:

- Garmin 011-05783-00 Manifold Pressure sensor has been updated to v2
- QPL-B200 MilSpec NP sensor has been updated to v2
- Garmin 011-05783-10 and 011-05783-20 are now available for Vacuum/De-ice pressure gauges

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

PRODUCTS AFFECTED

Table 1. Products Affected

System	Model	Appliance P/N
G500H TXi	GDU™ 700P	011-03306-20, -30
	GDU 700L	011-03307-20, -30
	GDU 1060	011-03308-20, -30
G500 TXi	GDU 700P	011-03306-20, -30
	GDU 700L	011-03307-20, -30
	GDU 1060	011-03308-20, -30
G600 TXi	GDU 700P	011-03306-60, -70, -80, -A0
	GDU 700L	011-03307-60, -70, -80, -A0
	GDU 1060	011-03308-60, -70, -80, -A0
G700 TXi	GDU 700P	011-03306-B0, -C0
	GDU 700L	011-03307-B0, -C0
	GDU 1060	011-03308-B0, -C0
EIS TXi	GDU 700P	011-03306-00, -10
	GDU 700L	011-03307-00, -10

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.