



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Piper PA-46-500TP Meridian Owner and Operators
DATE: May 5, 2022
SUBJECT: G1000® NXi STC Update for Piper PA-46-500TP Meridian
CERTIFICATION AUTHORIZATION: STC SA01947WI MDL Revision 5

COMPLIANCE

Recommended: Compliance with STC Service Bulletin 22045 is recommended at the next scheduled maintenance interval.

PURPOSE

This STC Service Bulletin provides notification of System Software v3880.02, which provides the following:

- Update to GTX™ 345(D)R ADS-B system software to address potential for missing or inaccurate ADS-B traffic targets as described in Garmin Service Advisory 2157
- Configuration update to enable checklist feature



NOTE

End user is responsible for obtaining any additional required approval for operational use of a checklist if implemented.

PRODUCTS AFFECTED

Piper PA-46-500TP Meridian aircraft equipped with G1000 NXi Integrated Flight Deck per STC SA01947WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.