



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** GTN™ Xi Owners and Operators  
**DATE:** August 8, 2022  
**SUBJECT:** GTN Xi Main Software Version 20.24, GPS/WAAS Version 8.2,  
COM Version 2.02, NAV Version 2.04, and GMA35/c Audio ARC  
DB Version 4.22C

---

### **COMPLIANCE**

Recommended: Compliance with this Service Bulletin is recommended at the next scheduled maintenance interval for installations with Main Software Version 20.10 through 20.23.

For all other installations this service bulletin is optional.

### **PURPOSE**

GTN Xi Series Main Software Version 20.24 fixes an issue with the use of the GPS Antenna Height Above Ground configuration setting. This setting is used to determine the GPS altitude of the airplane by compensating for the mounting height of the GPS antenna on the aircraft.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

## **PRODUCTS AFFECTED**

The following units are affected:

**Table 1. Products Affected**

<b>Model</b>	<b>Appliance P/N</b>
GTN 625Xi	011-04629-00
GTN 635Xi	011-04630-00
GTN 650Xi	011-04631-( )
GTN 725Xi	011-04632-00
GTN 750Xi	011-04634-( )
GMA™ 35	011-02299-2( )
GMA 35c	011-02299-4( )

## **WARRANTY INFORMATION**

For GTN Xi installations with Main Software Versions 20.10 through 20.23, this modification is warranty reimbursable with a deadline of August 31, 2023.

For all other installations this service bulletin is not warranty reimbursable.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.