



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 23070 Rev B

**TO:** GI 275 Owners and Operators  
**DATE:** August 28, 2023  
**SUBJECT:** RNAV approaches  
**REVISION B:** Added Resolution

---

### **PRODUCTS AFFECTED**

All GI 275 products with software versions 2.52 and later, interfaced with a GFC 500 autopilot are affected.

### **ISSUE**

When attempting to ARM a GPS approach for GPS/GP, the GI 275 may instead ARM the ILS approach LOC/GS.

### **ACTION**

For GPS approaches, tune the NAV source to an unused NAV frequency before arming the GPS Approach.

### **RESOLUTION**

This has been fixed in GI 275 System Software Version 3.01. Refer to Garmin TSO Service Bulletin 23087.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a  
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).