



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 23082 Rev A

TO: G1000® NXi, G2000®, G3000®, G5000® and GTN™ Xi Owners and Operators
DATE: August 14, 2023
SUBJECT: Incorrect Course Deviation Indicator (CDI) After Canceling Parallel Offset

PRODUCTS AFFECTED

The following products are affected:

- GTN Xi products with Software Versions 20.20 through 20.3X
- G1000 NXi and G2000/G3000/G5000 products with GDU™ Software Versions 32.00 through 32.10

ISSUE

When rejoining the non-offset course after canceling a parallel offset, the CDI may revert to displaying the deviation from the offset track.

ACTION

After rejoining the non-offset course, reactivate the current leg after capture and the CDI will correct itself.

RESOLUTION

This will be resolved in future software releases.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/)..