



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GI 275 Owner and Operators
DATE: September 25, 2023
SUBJECT: GI 275 ADAHRS + AP Power Fault Message
CERTIFICATION AUTHORIZATION: STC SA02658SE MDL Rev 22

COMPLIANCE

Optional: Compliance with this service bulletin is optional and may be incorporated at the owner's discretion.

PURPOSE

The GI 275 may show a power fault message. To prevent the GI 275 from sensing a power fault, a 1K Ohm series resistor is needed to increase impedance.

PRODUCTS AFFECTED

GI 275 ADAHRS + AP units connected to a Century IV, 41, or 2000 autopilot system installed using STC SA02658SE are affected.

WARRANTY INFORMATION

This modification is warranty reimbursable for installations completed before October 1, 2023, with a deadline of February 29, 2024.



NOTE

Installations completed after October 1, 2023 are not eligible for warranty reimbursement.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

DOCUMENTATION CONSIDERATIONS

There are no recommended AFMS or Pilot's Guide changes applicable to this bulletin. Applicable AFMS and ICA documents listed in Table 1, are required to be issued to the aircraft owner/operator before the aircraft is returned to service, if not already provided.

Table 1

Document Title	Part Number	Revision
GI 275 Part 23 AML STC Maintenance Manual with Instructions for Continued Airworthiness	190-02246-11	7
GI 275 Part 23 AML STC AFMS	190-02246-12	10

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.