



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** GFC 500 Cirrus SR22 aircraft Owner and Operators  
**DATE:** June 3, 2024  
**SUBJECT:** Approval of an updated manual electric trim (MET) speed for Cirrus SR22 aircraft  
**CERTIFICATION AUTHORIZATION:** STC SA01866WI MDL Revision 90

---

### **COMPLIANCE**

Optional: STC Service Bulletin 24049 may be incorporated at the owner's discretion.

### **PURPOSE**

This STC Service Bulletin provides notification of an update to STC SA01866WI, GFC 500 STC, MDL Revision 90.

Revision 90 approves GI 275 Software Version 3.10 and G5 Software Version 8.26. These software versions are required to update the manual electric trim (MET) speed setting.

### **PRODUCTS AFFECTED**

GFC 500 autopilot systems installed in Cirrus SR22 aircraft using GFC 500 Part 23 AML STC SA01866WI are affected.

### **DOCUMENTATION CONSIDERATIONS**

The *Airplane Flight Manual Supplement GFC 500 Autopilot with ESP™ Installed in Cirrus SR22*, 190-02291-55 Rev. 4 must be provided to the aircraft operator/owner.

### **WARRANTY INFORMATION**

This Service Bulletin is not warranty reimbursable.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.