



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: G500/G600/G700 TXi Owners and Operators
DATE: August 2, 2024
SUBJECT: G500/G600/G700 TXi GEA 71B System Software Version 2.92
CERTIFICATION AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Optional: This service bulletin may be incorporated at the owner's discretion.

PURPOSE

G500/G600/G700 TXi GEA 71B System Software Version 2.92 corrects the GEA annunciator outputs during start-up.



NOTE

Database sync routing is affected by this change. Systems with GTN (v6.72 or earlier) or GPS 175/GNC® 355/GNX™ 375 (v3.11 or earlier) interfaced to G500(H)/G600/G700 TXi (v3.50 or later) or GI 275 (v2.60 or later) no longer support database sync. Databases will need to be loaded onto each GTN and GPS 175/GNC 355/GNX 375 unit. This has been fixed in GTN software v6.73. This limitation will be fixed in future GPS 175/GNC 355/GNX 375 software versions.

© 2024 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

PRODUCTS AFFECTED

Table 1. Products Affected

System	Model	Appliance P/N
G500 TXi	GDU 700P	011-03306-20, -30 011-03306-22, -32
	GDU 700L	011-03307-20, -30 011-03307-22, -32
	GDU 1060	011-03308-20, -30 011-03308-22, -32
G600 TXi	GDU 700P	011-03306-60, -70, -80, -A0 011-03306-62, -72, -82, -A2
	GDU 700L	011-03307-60, -70, -80, -A0 011-03307-62, -72, -82, -A2
	GDU 1060	011-03308-60, -70, -80, -A0 011-03308-62, -72, -82, -A2
G700 TXi	GDU 700P	011-03306-B0, -C0 011-03306-B2, -C2
	GDU 700L	011-03307-B0, -C0 011-03307-B2, -C2
	GDU 1060	011-03308-B0, -C0 011-03308-B2, -C2

WARRANTY INFORMATION

This modification is not warranty reimbursable.

DOCUMENTATION CONSIDERATIONS

The G500(H)/G600/G700 TXi Pilot's Guide (190-01717-10) Rev P is to be provided to the owner/operator if not already provided.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.