

1200 E. 151<sup>st</sup> Street Olathe, KS 66062 913-397-8200

# SERVICE ADVISORY

NO.: 24062 Rev A

TO:	GI 275 Owners and Operators
DATE:	July 31, 2024
SUBJECT:	VNAV in GFC <sup>™</sup> 500 Automatic Flight Control Systems

## PRODUCTS AFFECTED

GI 275 Multi-function Instruments interfaced to GFC 500 systems are affected.

#### <u>ISSUE</u>

The GFC 500 will not activate VNAV when in a holding pattern and the TOD (Top of Descent) is on the outbound leg.

### **ACTION**

Make sure the TOD is on the inbound leg of the holding pattern after arming VNAV.

#### RESOLUTION

This will be fixed in a future GI 275 software release.

© 2024 Garmin Ltd. or its subsidiaries. This work is licensed under a <u>Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License</u>..

Service Advisory 24062 July 31, 2024 Page 1-1 Revision A