



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 24067 Rev B

TO: GTN™ Touchscreen Avionics and GTN Xi Owners and Operators
DATE: October 16, 2024 (Originally Issued August 22, 2024)
SUBJECT: GTN Xi Crossfill
REVISION B: Revised to make more encompassing

PRODUCTS AFFECTED

GTN Xi Garmin navigators with Software Version 20.30 and later, crossfilled to non-GTN Xi Garmin navigator are affected.



NOTE

GTN Xi navigators crossfilled with GTN Xi navigators are not affected. GTN navigators crossfilled with GTN units are also not affected.

ISSUE

When GTN Xi Garmin navigators are interfaced with a non-GTN Xi Garmin navigator, differences between the two navigators may result in minor discrepancies in the active flight plan, course depictions, and turn annunciations, even while the Crossfill function is active.

ACTION

Use the GTN Xi Garmin navigator as the primary navigator.

RESOLUTION

If the discrepancy is affecting pilot workload, disable crossfilling and delete the flight plan from the non-GTN Xi Garmin navigator.

© 2024 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).