



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GMA™ 342/345 Audio Panel Owner and Operators
DATE: December 5, 2024
SUBJECT: GMA 342/345 System Software Version 2.40
CERTIFICATION
AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Recommended: Compliance with this service bulletin is recommended at the next maintenance interval.

PURPOSE

GMA 342/345 System Software Version 2.40 includes the following enhancements:

- Fixed an issue that caused the GMA 345 to not appear discoverable when in Bluetooth pairing mode (-00 and -20 only)
- Fixed an issue that occasionally prevented Bluetooth audio from being heard (-00 and -20 only)
- Added support for new hardware versions GMA 342 (011-03520-11), GMA 345 (011-03520-01), and GMA 345 3-COM (011-03520-21)

PRODUCTS AFFECTED

GMA 342 011-03520-1(), GMA 345 011-03520-0(), and GMA 345 3-COM 011-03520-2() units are affected.

WARRANTY INFORMATION

This modification is warranty reimbursable with a deadline of May 31, 2025 for the -00 and -20 only.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.