



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GIA 64, GTR 20, GTR 200, and GTR 200B Owner and Operators
DATE: January 6, 2025
SUBJECT: COM Transmitter

COMPLIANCE

MANDATORY: Compliance with this service bulletin is mandatory.

PURPOSE

A component in the COM transmitter power supply can cause the COM transmitter to output excessive RF (radio frequency) power which can damage the COM transmitter and receiver hardware.

This service bulletin provides instructions to remove and replace any affected units. The affected unit may be repaired (if repairable) and returned at the customer's request.

PRODUCTS AFFECTED

GIA 64, GTR 20, GTR 200, and GTR 200B units purchased or installed since August 2024 and listed in the link below are affected.

<https://support.garmin.com/en-US/aviation/faq/mKZBAv7Arz5IeNrLBfm5W6>

WARRANTY INFORMATION

This Service Bulletin is warranty reimbursable with a deadline of January 31, 2026 after which this upgrade will no longer be reimbursable for labor.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.