



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GI 275/275D Owners and Operators
DATE: June 17, 2026
SUBJECT: GI 275/275D Multi-function Instrument System Software Version 3.50
CERTIFICATION AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Recommended: Compliance with this service bulletin is recommended at the next maintenance interval.

PURPOSE

GI 275/275D Multi-function Instrument System Software Version 3.50 adds the following.

GI 275 -00 through -70:

- Corrected issue with ILS Only via ARINC 429
- Improved system message alerting
- Improved ADAHRS Reversion Annunciation and Messaging
- Various UI and Display Improvements
- Improved the download of flight logs
- Improved the content of flight logs
- Added support for Second Standby ADAHRS Source
- CDI Page can now show split sourced navigation when using active VNAV and VHF NAV based lateral deviations
- Added HSI Orientation – Allows for Track centered navigation
- Added optional filtering to ADAHRS Outputs over ARINC 429
- Expanded configurable range for pitch recovery chevrons
- Improved Config Summaries

© 2026 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

GI 275D -80:

- Improved system message alerting
- Added support for Second Standby ADAHRS Source
- Expanded configurable range for pitch recovery chevrons
- Improved Config Summaries

PRODUCTS AFFECTED

GI 275/275D Multi-function Instruments listed below with System Software Version 3.44 or earlier are affected.

Table 1. Product Affected

Model	Appliance P/N
GI 275	011-04489-00 through -70
GI 275D	011-04489-80

WARRANTY INFORMATION

For the GI 275 -00 through -70 units only, labor reimbursement is available for modifications completed by December 31, 2026, or within the equipment's original factory warranty period.



NOTE

Labor Reimbursement is not available for the GI 275D -80.

DOCUMENTATION CONSIDERATIONS

Rev T of the GI 275 Pilot's Guide (190-02246-01) and Rev C of the GI 275D Pilot's Guide (190-03060-00) are the latest revs at time of publication.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.