AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GTR 225/GNC 255 Owner/Operators

DATE: October 1, 2013

SUBJECT: GTR 225/GNC 255 Software Upgrade to COM Software Version 2.12

CERTIFICATION

APPROVAL: TSO Authorization (see Approval section of SSB 1354 for details)

COMPLIANCE

Optional

PURPOSE

This Service Bulletin announces the availability of GTR 225/GNC 255 COM Software Version 2.12.

COM Software Version 2.12 contains the following changes from Version 2.11:

- COM Software Version 2.12 provides improved squelch control over Version 2.11. It is helpful only in those installations that experience open squelch (receiver too sensitive) after utilizing the COM Monitor Mode.

PRODUCTS AFFECTED

The following units are affected:

	GTR 225	GTR 225A	GTR 225B	GNC 255A	GNC 255B
Garmin PN	011-02718-00	011-02807-00	011-02808-00	011-02806-00	011-02719-00
COM SW PN/ COM SW Version	006-B1061-06/ 2.12	006-B1061-06/ 2.12	006-B1061-06/ 2.12	006-B1061-06/ 2.12	006-B1061-06/ 2.12

DESCRIPTION

This software service bulletin describes the process for upgrading the GTR 225/GNC 255 Series Unit's COM Software to Version 2.12.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.