GARMIN.

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GDL 84/88 Owner/Operators
DATE: October 22, 2015

SUBJECT: GDL 84/88 Software Upgrade to System Software Version 3.32 for Non-GX000 Integrated Flight Deck Installations Only

CERTIFICATION
APPROVAL: TSO

COMPLIANCE
Optional.

PURPOSE
GDL 84/88 System Software Version 3.32 contains the following changes from Version 3.20:
- GDL 90 Emulation/Legacy ADS-B Interface support (GDL 88 only)
- Removed ground traffic from ARINC 429 Traffic Out interface (GDL 88 only)
- Various processing efficiency improvements and minor bug fixes

PRODUCTS AFFECTED
All GDL 84/88 units listed in the table below interfaced to a GTN 6XX/7XX, GNS 4XXW/5XXW, GNS 480, GMX 200/MX20, G500, G600, or other 3rd party flight display system are affected.

	GDL 88	GDL 88 w/WAAS	GDL 88D	GDL 88D w/WAAS	GDL 84
Garmin PN	011-02369-00	011-02370-00	011-02371-00	011-02372-00	011-03727-00
System SW PN/ System SW Version	Versions prior to 006-B0684-15/ 3.32	Versions prior to 006-B0684-15/ 3.32	Versions prior to 006-B0684-15/ 3.32	Versions prior to 006-B0684-15/ 3.32	006-B0684-12/ 3.20

	GDL 88H	GDL 88H w/WAAS	GDL 88DH	GDL 88DH w/WAAS	GDL 84H
Garmin PN	011-02369-10	011-02370-10	011-02371-10	011-02372-10	011-03728-00
System SW PN/ System SW Version	Versions prior to 006-B0684-15/ 3.32	Versions prior to 006-B0684-15/ 3.32	Versions prior to 006-B0684-15/ 3.32	Versions prior to 006-B0684-15/ 3.32	006-B0684-12/ 3.20

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.