GARMIN.

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record of G1000-equipped King Air 200/300 Series Aircraft
DATE: February 17, 2017

SUBJECT: G1000 System Software Version 2286.01 and new NXi hardware for G1000-equipped King Air 200/300 Series

CERTIFICATION APPROVAL: STC SA01535WI-D

COMPLIANCE
Optional

PURPOSE
New hardware:

- Flight Stream 510 for data streaming and database updates

- GDU 1050A/1550 NXi display hardware

- GCU 477 NXi keypad controller

- GTX 345R transponder for ADSB-In data display

> **NOTE**
>
> The GTX 345R replaces GTX 33 #1. It cannot replace a GTX 33D in EASA registered aircraft or a GTX 3000 unit for TCAS II equipped aircraft.

G1000 System Software Version 2286.01 contains the following changes:

- Nexrad animation

- Visual approach support

- Flight plan auto-nomination

- Transition to approach

- SurfaceWatch

- Vertical situation display

- HSI map

- Visual reporting points

- IFR/VFR maps

- GWX 70 radar ground clutter suppression and turbulence detection

- Dual charts to allow pilot selection of FliteCharts or ChartView for display

PRODUCTS AFFECTED
All G1000-equipped King Air 200 and 300 series aircraft equipped with G1000 System Software Versions 0985.01, 0985.02, 0985.03, 0985.04, 0985.05, 0985.06, 0985.07, 0985.08, or 0985.09 are affected.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.