**AVIATION SERVICE DOCUMENT NOTIFICATION**

| | |
|---|---|
| **TO:** | Garmin G500/G600 TXi Owner and Operators |
| **DATE:** | July 31, 2019 |
| **SUBJECT:** | Approval of G500/G600 TXi v3.02, Single Turbine Engine Indication System (EIS) |
| **CERTIFICATION AUTHORIZATION:** | STC SA02571SE MDL Revision 7 and EASA STC 10064794 MDL Revision 7 |

---

## COMPLIANCE

Optional:  This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

## PURPOSE

MDL revision 7 includes the following changes:

- TXi software v3.02
- AHRS software v2.08
- ADC software v2.07
- GPS 175/GNX 375 interface approval
- Collins APS 65 interface approval
- Added the following aircraft to the Approved Model List:
  - Mitsubishi MU-2 series
  - Airvan10 GA 10
  - Tecnam P2010

The TXi G500/G600 software v3.02 update includes the following changes:

- EIS support for single engine turbine aircraft equipped with PT-6A engines
- Exceedance monitoring capability
- Electrical gauge improvements
- Additional FIS-B products
- APS 65 interface support
- Increased the volume level of the emergency descent audible annunciation
- Removed the YTRIM annunciation

## PRODUCTS AFFECTED

G500/G600 TXi PFD/MFD/EIS display systems installed using Approved Model List (AML) Supplemental Type Certificate (STC) SA02571SE and EASA STC 10064794 are affected.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.