

1200 E. 151st Street Olathe, KS 66062 913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: G1000® Flight Deck Owner and Operators

DATE: March 5, 2024

SUBJECT: G1000 System ID Tool

COMPLIANCE

Recommended: Compliance with Service Bulletin 0736 is recommended before March 12, 2024. Failure to do so will result in loss of aviation databases.

PURPOSE

Garmin has identified an error associated with G1000 system software upgrades that sometimes results in an invalid System ID. An invalid System ID can be identified as either being "00000000" or "20000000". The G1000 System ID can be verified on the AUX-System Status Page (Figure 1).



NOTE

The G1000 System ID is only displayed on GDU's with GDU software version 6.00 or later.



Figure 1 Example AUX – System Status Page

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



Olathe, KS 66062 913-397-8200

PRODUCTS AFFECTED

All GDU 1XXXs with a GDU software version of 7.00 or greater **and** a System ID of "00000000" or "20000000". The G1000 System ID can be verified on the MFD AUX-System Status Page (Figure 1).

WARRANTY INFORMATION

This modification is not warranty reimbursable.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.