



SERVICE ADVISORY

NO.: 1138 Rev A

TO: Owners/Operators with GTN 6XX/7XX Units
DATE: December 2, 2011
SUBJECT: GTN 6XX/7XX Units and 'Data Source' Error Messages

AFFECTED PRODUCTS

GTN 6XX/7XX Units with Main Software Version 2.00.

DESCRIPTION

When the GTN inputs are configured for certain traffic or altitude formats, one or both of the following messages may be displayed:

'DATA SOURCE - Heading source inoperative or connection to GTN lost'

'DATA SOURCE - Pressure altitude source inoperative or connection to GTN lost'

This message will persist throughout the power cycle. Once viewed, it stops blinking. For aircraft in which a heading source or pressure altitude source is not connected to the GTN, the message(s) are nuisance messages only. For aircraft in which a heading source or pressure altitude source is connected to the GTN, the message(s) function correctly, appearing only if the GTN is not receiving heading or pressure altitude information.

PILOT ACTION

No pilot action is necessary.

RESOLUTION

Garmin plans to correct this issue in software version 3.00.

© Copyright 2011
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.