



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin Owners/Operators

DATE: 09 November 2011

SUBJECT: This communication is intended to inform Garmin aviation customers of forthcoming service document Software Service Bulletin 1153: Software Version 6.20 available for GTX 330/330D w/ES (Extended Squitter) products (not applicable to GNS 480, G900X, G950, G1000, Cirrus Perspective®, or Embraer Prodigy™ installations)

COMPLIANCE

Optional: Software Service Bulletin 1153 may be incorporated at the customer's request.

PURPOSE

Software Version 6.20 for GTX 330/330D w/ES products (not applicable to GNS 480, G900X, G950, G1000, Cirrus Perspective®, or Embraer Prodigy™ installations) improves the quality of transmitted position information.

PRODUCT AFFECTED

Software Service Bulletin 1153 is applicable to GTX 330/330D w/ES (Extended Squitter) units with Software Version 6.11 or previous software versions that are not installed with GNS 480, G900X, G950, G1000, Cirrus Perspective®, or Embraer Prodigy™ systems.

NOTE

This software service bulletin does not apply to non-ES enabled GTX 330/330D units.

The unit's current software version is displayed at power up on the GTX 330/330D front panel.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.